
Mark's Model Works 1/64th scale New Zealand Native Birds Instruction sheet Walking and wading Birds



- 1. Carefully drill a hole in the body for the legs
- 2. Gently clean the brass and remove the "bird" from the etch



- 3. Use some fine wire for the legs, bend together
- 4. Solder or glue the wire to the body



- 5. Build up the body with solder, glue, putty or layers of paints
- 6. Paint bird to prototype colours

Perched Birds





- 1. Gently clean the Bird and remove from the etch with a sharp knife
- 2. Hold the tail in a vice or pilers





3. Twist the body and tail 90°





- 4. Hold the tail and build up the body with solder, glue, putty or layers of paint
- 5. Paint bird to the prototype

The Etch can also be polished, lacquered, mounted and framed as art work.